



Care & Maintenance

Your Stor-Mor Shed will need care and maintenance to sustain its functionality and looks.

Redirect all Water – Water is not a friend of wood structures. Make sure to redirect water from your building whenever possible. Damage caused by rain water runoff from other structures or misdirected sprinkler systems is not covered by your Stor-Mor warranty.

Keep your building leveled – Over time, normal ground settling can occur, making it difficult to open, close or latch the shed door. This is not a warranty issue, but in most cases, the shed can often be easily re-leveled by the customer or by Stor-Mor Sheds for a fee.

Repaint regularly - Painting protects the exterior wood surface of your building. Your building's warranty coverage requires that the building be repainted every eight years.

Ventilation – When installing a shed on dirt or grass, it is imperative that air flow is not trapped around the floor, as this will most likely lead to moisture problems over time. Our wood framed floor buildings are constructed on concrete patio blocks and our steel framed floors have air holes for ventilating purposes. Blocking either the holes on the steel frame or the gap under the building created by the patio blocks will likely trap moisture under the building and cause damage to the floor. Settling that occurs over time, resulting in a blockage to this air gap, may also cause damage. This is not a warranty issue covered by your Stor-Mor warranty.

Appearance of your Building

An unfinished interior can create several questions as you inspect the appearance of your new building. Here are some explanations to issues you may notice:

Roofing nails – it is normal for roofing nails to poke through the roof on the inside of your building. This is necessary due to building codes requiring shingle nails to pierce the roof decking material and does not affect the performance of the roof.

Lumber – it is unlikely that the dimensional lumber we use will have a uniform appearance. You may see blemishes or waning in the lumber, but be assured this is normal and will not affect the structural integrity of your building.

Steel – Our steel framed floor is left in a galvanized state and chalking may occur. Rest assured that this is normal.

Weather tight or Airtight – While we strive to make all our buildings weather tight, they are not airtight. Air and mice can infiltrate your building as they can your home.

Paint – Our painting option applies to the exterior surface of your building only. We do not offer interior painting.